


BAUMANN LAND SURVEY, INC.

2008 CENTRAL AVENUE
CINCINNATI, OHIO 45214
513.860.3999
BAUMANNLSI.COM



OHIO WEST VIRGINIA KENTUCKY TENNESSEE INDIANA ILLINOIS IOWA SOUTH DAKOTA



Project: Forensic Pipe Scan

Location: Ohio

Client: Contractor

Baumann Land Survey, Inc. provided forensic surveying services to the client for use in a multi-million dollar lawsuit. The inside of large diameter steel pipes were scanned to measure pipe ovality and weld geometry. Due to the legal settlement, no project data or images were retained. Images shown on this sheet are only a representation of work performed.